


## “REDEYE” FAULT SHEET

Client	XXXXXXX	Report No.	06XX/1
Thermographer	F Salvoldi	Sheet No.	1
Date Inspected	22 March 2006	Tape Ref.	08:59

Line	XXXXXXXXXXXXXXXXXXXX		
Tower No / Span	48	Tower Type	Strain
Phase / EW	Left Phase	Quad / % Span	B
Component	Compression Deadend, compression side		

Temperature	
Component Temp.	74°C
Conductor Temp.	22°C
Temp. Difference	52°C
Load	A
Cause	
Loose Component	
Faulty Component	X
Overload	
Other	
Remedy	
Clean	
Tighten	
Repair	
Replace	X
Other	

Notes/Picture/Sketch



Signature	
Date	27/03/06

REPAIR PRIORITY

